



Clamp Multimeter MD-410C

Order code: M0400

THE MOST IMPORTANT PARAMETERS

Parameter	Value
range selection	automatic
AC voltage	4-600 V
AC current	400 A
DC voltage	400 mV - 600 V
DC current	400 A
electrical resistance	400 Ohm - 40 MOhm
circuit continuity	yes

OTHER PARAMETERS

Parameter	Value
diode test	yes
transistor test	no
non-contact AC voltage detection	no
contact AC voltage detection	no
battery test	no
temperature measurement	-20 °C to +1 000 °C
max. value hold	no
Data hold mode	yes
auto power off	yes
screen display	3 3/4 digit
backlight display	no
low battery indication	yes
clamp multimeter	yes
dimensions	38 x 71 x 194 mm
included	battery, manual, measurement tips
power source	2x 1.5 V AAA (included)
packaging	1 pc, blister